



# Phased Array Ultrasonic Testing (PAUT) Weld Flaw Characterization Chart

Use this handy reference sheet to help you interpret the flaws detected by your OmniScan® flaw detector



# Phased Array Ultrasonic Testing (PAUT) Weld Flaw Characterization Chart

Use this handy reference sheet to help you interpret the flaws detected by your OmniScan® flaw detector



[www.olympus-ims.com](http://www.olympus-ims.com)

**OLYMPUS**

OLYMPUS CORPORATION OF THE AMERICAS  
48 Woerd Avenue, Waltham, MA 02453, USA, Tel.: (1) 781-419-3900  
110 Magellan Circle, Webster, TX 77598, USA, Tel.: (1) 281-922-9300

OmniScan and Olympus are registered trademarks of Olympus Corporation.